CIVIL PRO
AN ISO 9001 : 2008 COMPANY & NABL ACCREDITED LABORATORY AS PER ISO/IEC 17025:2017
4, 7TH MAIN MALLESWARAM, BANGALORE -3
Certificate No.: TC-5548

Date: 09-06-2021

To,

ASSISTANT EXECUTIVE ENGINEER
YELAHANKA SATELLITE SUB DIVISION
BBMP
BANGALORE

Dear Sir,

Sub: M/s. Civil Pro Services for the work of "PROVIDING POTHOLE FILLING IN WARD NO.04"

Ref: 1. Work Order No: BBMP/EE/YNK.D/EPMT-01/W.O/76/2020-21

2. Job code: 04-20-000143

We are herewith forwarding to Sri S Somashekar, No:15/44/1 Allalasandra, GKVK Post, Yelahanka, Bangalore-560065. First and Part bill duly verified and certified that the Work is satisfactory and for a Gross Value of Rs.9,99,500/-(Rs. Nine Lakhs Ninety Nine Thousand and Five Hundred Only).

Thanking you,

Yours faithfully,

For Civil Pro

CIVIL Pro Sig..... Date..... BANGALORE

R KARTHIK RECHAN
AUTHORIZED SIGNATORY
CIVIL PRO

ಸಹಾಯಕ ಕಾರ್ಯನಿರ್ವಾಹಕ ಅಭಿಯಂತರರ ಯಲಹಂಕ ಉಪನಗರ ಉಪವಿಭಾಗ. ಬಿ.ಬಿ.ಎಂ.ಪಿ. ಬೆಂಗಳೂರು-100

AE

CIVIL PRO
AN ISO 9001 : 2008 COMPANY & NABL ACCREDITED LABORATORY AS PER ISO/IEC 17025:2017
4, 7TH MAIN MALLESWARAM, BANGALORE -3
Certificate No.: TC-5548

QC ABSTRACT

NAME OF WORK: "Providing Pothole Filling in Ward No 04."

SL NO	Item Of Work	Name of Test	Frequency of Test/Quantity	Executed Quantity	Number of Tests Required	Number of Tests Conducted
		Materials				
1	GSB	SIEVE ANALYSIS	One Test		1	1
2	WMM	Sieve Analysis	One Test		1	1
		Impact Value	One Test		1	1
		Flakiness Index	One Test		1	1
		Elongation Index	One Test		1	1
3	DBM	SIEVE ANALYSIS	One Test		1	1
		STRIPPING VALUE	One Test		1	1
		Flakiness Index	One Test		1	1
		Elongation Index	One Test		1	1
		IMPACT VALUE	One Test		1	1
		Specific gravity	One Test		1	1
		Water Absorption	One Test		1	1
		Marshal Stability	One Test		1	1
		Marshal flow	One Test		1	1
		Percent air Voids	One Test		1	1
		Percent Voids in mineral Aggregate	One Test		1	1
		Percent Voids filled with Bitumen	One Test		1	1
		Density	One Test		1	1
		Gradation	One Test		1	1
4	BC	SIEVE ANALYSIS	One Test		1	1
		STRIPPING VALUE	One Test		1	1
		Flakiness Index	One Test		1	1
		Elongation Index	One Test		1	1
		IMPACT VALUE	One Test		1	1
		Specific gravity	One Test		1	1
		Water Absorption	One Test		1	1
		Marshal Stability	One Test		1	1
		Marshal flow	One Test		1	1
		Percent air Voids	One Test		1	1
		Percent Voids in mineral	One Test		1	1
		Percent Voids filled with Bitumen	One Test		1	1
		Density	One Test		1	1
		Gradation	One Test		1	1
5	BITUMEN	Ductility	One Test		1	1
		Softening Point	One Test		1	1
		Penetration	One Test		1	1
		Flash Point	One Test		1	1
		Fire Point	One Test		1	1
6	TACK COAT	Rate of spread	One Test		1	1
7	Thermoplastic Compound	Colour	One Test		1	1
		Softening Point	One Test		1	1
		Luminance Factor	One Test		1	1
		Cracking Resistance	One Test		1	1
		Skid Resistance	One Test		1	1
		Yellow Index (For White Thermoplastic Plant)	One Test		1	1
		Drying Time	One Test		1	1
		Binder Content	One Test		1	1
		Glass Beads Content	One Test		1	1

AE

M : 9972924526 | Tel : +91 80 23444801 | e : rechan6630@yahoo.co.in, civilproexperts@gmail.com